

Fox Rehabilitation Signage Chart			
Sign #	Existing or Proposed	Description and Location	Relief Required
Sign #1	Existing	Main entrance monument sign located at eastern driveway entrance	No relief sought or required
Sign #2	Existing	Main entrance façade logo sign located on the Carnegie Avenue/south elevation of the building	No relief sought or required
Sign #3	Existing	Fox Track – walking path sign near front entrance	*This sign was removed by Fox Rehab. Photos showing removal will be supplied
Sign #4	Existing	Front door logo and hours	No relief sought or requested
Sign #5	Existing	Employee entrance monument sign located at western driveway entrance	(2) Variances are sought to permit 2 freestanding signs where 1 is permitted and to allow the text "Employee Entrance" below 3' from grade level.
Sign #6	Existing	Front parking lot directional sign located in southern parking lot area	No relief sought or required
Sign #7	Existing	Fox EDU entrance sign located along the northern elevation of the building	No relief sought or required
Sign #8	Existing	Ameriflex entrance sign located along northern elevation of the building	(2) Variances are sought to permit additional façade sign where only 1 is allowed and to allow a façade sign affixed to a building elevation with no street frontage
Sign #9	Existing	Fox MVP parking sign	No relief sought or required
Sign #10	Existing	Side door employee entrance located on a side entrance door	No relief sought or required
Sign #11	Existing	Fox Track – walking path sign located in western parking lot area	*This sign was removed by Fox Rehab. Photos showing removal will be supplied
Sign #12	Existing	Executive entrance door sign located on a side entrance door	No relief sought or required
Sign #13	Proposed	South Jersey Auto Bid façade sign proposed to be located along the northern elevation of the building	(2) Variances are sought to permit additional façade sign where only 1 is allowed and to allow a façade sign affixed to a building elevation with no street frontage